

Oil Field Environmental Incident Summary

Incident: 20160708170059 **Date/Time of Notice:** 07/08/2016 17:00

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: Dakota Pipeline Access - 156N-R95W Section 31

Field Name:

Well File #:

Date Incident: 7/6/2016

Time Incident: 12:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 95

Sec: 26

Qtr: SE SE

Location Description: Dakota Access Pipeline - LAT: 48.286634 LONG: -102.938713. Pipeline excavation located approximately 1,600 feet northwest of the intersection of 104th Avenue NW and 60th Street NW

Submitted By: Alberto Yates

Received By:

Contact Person: Troy Brunsell
3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.6 Mile

Distance Nearest Water Well: 0.6 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Potential hydrocarbon-impacted soil discovered in the excavation while installing a new pipeline.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time.

Action Taken or Planned:

Upon discovery of the release, a vacuum truck was dispatched to recover the free liquids. Based on the information provided to the Hess Environmental Team and Site conditions observed during the reconnaissance, the source of the potential impacts cannot be determined at this time. To determine involvement moving forward, Hess Environmental Team / Earth Systems would like to collect additional information and soil samples near the pipeline excavation. Arrangements were made for the impacted material to be cleaned up and disposed of to an approved waste facility.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 7/11/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, a release was discovered during pipeline operations. Further follow-up is needed.

Date: 7/19/2016 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site at 9:30 a.m. 75 degrees, raining and thunderstorm. Wind 11 mph SE. When arriving on site, all personnel were on a safety stand-down due to lightning. After the storm had passed, inspection was conducted. Spoke to on-site personnel with Pyramid Env. And Hess. Apparent old abandoned pipe was uncovered while digging, and apparent previous historical contamination was uncovered. Oil had already been pumped out of the trench. The pipe which had leaked appeared to be old with several holes in it. At time of inspection, no oil was seen. Some water was seen in the bottom of the trench.